

Notice de montage
Mini F-15C
Ech 1:144



V1.0N
Page 3



V1.0A
Page 5




(FR) Conseils pratiques:

- Préparez les pièces (ponçage/ébavurage) pour améliorer le niveau de finition.
- La première couche des impressions FDM étant souvent écrasée, il y a souvent une arrête débordante à ébavurer à ces endroits,
- Utilisation de glue cyano ou colle époxy.
(je conseille un mix de cyano: à prise lente pour les grandes surfaces difficiles à ajuster comme les fuselages, et de la cyano à prise rapide pour les petits éléments)
- Peindre les pièces avant assemblage + peindre les finitions éventuelles après assemblage.
- Ne pas utiliser trop de colle pour éviter les débordements.
(et la dégradation de la peinture)
- Essayer d'assembler chaque étape avant de coller. (Assemblage a blanc)
- Poncer les surfaces à coller avant d'assembler
(le mieux étant de ne pas peindre les surface en contact des collages)
- Des retouches de peinture + un vernis de finition appliqués à la fin de l'assemblage peut améliorer le rendu.

V1.0N

1 Page 3-4




(EN) Practical tips:


- Prepare parts (sanding/deburring) to improve finish.
- The first layer of FDM prints is often crushed, so there is often an overflowing edge to be deburred in these places.
- Use cyano glue or epoxy glue.
I recommend a mix of cyano: slow cyano for large surfaces that are difficult to adjust, such as fuselages, and fast cyano for small parts
- Paint parts before assembly + paint any finishing touches after assembly.
- Don't use too much glue to avoid overload (and paint degradation)
- Try to assemble each step before gluing.
- Sand the surfaces to be glued before assembly
(the best way is not to paint the surfaces in contact with the gluing).
- Paint retouching + a finish varnish applied at the end of the assembly can improve the rendering.

V1.0A


1 Page 5 to 8




2 V1.0N




3




Wings & Stabs angles View



4



5




7



End


6




8




2 V1.0A



3




4




5


⚠ Use a flat surface to assure the alignements




6  Use a flat surface to assure the alignements




8



7




Wings & Stabs angles View (F-15 is flat)




9A

Landing gears Option



9B

Stand Option



Post treatment & varnished



End